944-SPEC - 944SPEC - low cost wheel to wheel racing Generated: 6 September, 2025, 16:23

ted by 944cer - 21 Jul 2008 01:17	
st noticed some slopiness in one of the stering rods. Is there a way to tighten this rod in the stering to I have a power stering rack that has been converted to manual (pump, resevoir removed and he ped back to rack). The play appears to be at the rack and not the end links.	-
anks,	
e:Loose Stering Rod ted by 944cer - 22 Jul 2008 22:58	
worries. I get in touch with them.	

\_\_\_\_\_\_